

SL-138

1975



E. D. Appolonia Consulting Engineers, Inc.

10 DUFF ROAD PITTSBURGH, PA. 15235

## DEPARTMENT OF ENVIRONMENTAL RESOURCES REVIEW NOTICE

This report, prepared by outside consultants, has been reviewed by the Department of Environmental Resources and approved for publication. The contents indicate the conditions that are existing as determined by the consultant, and the consultant's recommendations for correction of the problems. The foregoing does not signify that the contents necessarily reflect the policies, views, or approval of the Department

## TABLE OF CONTENTS

	•	_		
1Qt	Λt	Ta	n	PC

List	of	Fig	ures

1.0	Introduction		
2.0	Mining History		
3.0	Geology		
4.0	Field Investigation	4	
	4.1 Surficial Reconnaissance	4	
	4.2 Exploratory Excavation	6	
	4.3 Subsurface Investigation	6	
	4.4 Water Quality Analysis	7	
5.0	Abatement Methods	9	
	5.1 King No. 2 Mine	10	
	5.2 North Side of North Branch	11	
	5.3 South Side of North Branch	12	
	5.4 Estimated Construction Cost Effectiveness	13	
6.0	Recommendations	14	
7.0	Conclusion	15	

Tables

Figures

## **LIST OF FIGURES**

Figure No.	<u>Title</u>
1	Vicinity Map
2	Site Plan
3	Generalized Stratigraphic Column
4	Original Plan, of Excavations
5	Mine Conditions Exposed by Exploratory Excavation and Proposed Sealing Methods North Side of North Branch
6	Mine Conditions Exposed by Exploratory Excavations and Proposed Sealing Methods South Side of North Branch
7	Original Plan of Borings
8	Subsurface Investigation, Boring Logs 1, 2, 4, 5, 6 and 7
9	Subsurface Investigation, Boring Logs 8 and 10
10	Typical Water Quality Data - Sampling Date 7-2-70
11	Mine Discharge Water Quality Sampled May and September 1970
12	Plan, Sealing King No. 2 Mine Complex
13	Plans, Sealing North Branch Mine Complex
14	Construction Details of Deep Mine Sealing

## LIST OF TABLES

Table No.	<u>Title</u>
1	Hydraulic Pressure Test Results, Cucumber Run
II	Water Quality and Pollution Load, Cucumber Run
III	Construction Cost Estimate, Mine Sealing, Cucumber Run Watershed