# COMMONWEALTH OF PENNSYLVANIA


## DEPARTMENT OF MINES

AND

# MINERAL INDUSTRIES

OPERATION SCARLIFT PROJECT NO. SL-108

# ACID MINE DRAINAGE SURVEY EAST BRANCH CLARION RIVER WATERSHED ELK AND McKEAN COUNTIES



PREPARED BY

MICHAEL BAKER, JR, INC. CONSULTING ENGINEERS ROCHESTER, PENNSYLVANIA

# MICHAEL BAKER, JR., INC.

#### THE BAKER ENGINEERS

BRANCH OFFICES

JACKSON, MISSISSIPPI HARRISBURG, PENNSYLVANIA CHARLESTON, WEST VIRGINIA



# Consulting Engineers Planners Surveyor.

P. O. BOX 111

ROCHESTER, PENNSYLVANIA - 15074

AREA CODE 412 - PHONE 774-3010

December 1970

Honorable H. B. Charmbury, Secretary Department of Mines and Mineral Industries Commonwealth of Pennsylvania 660 Boas Street Harrisburg, Pennsylvania 17102

Subject:

Operation Scarlift

Project No. SL-108

East Branch Clarion River

Dear Dr. Charmbury:

We hereby submit the following report on acid mine drainage within the East Branch Clarion River Watershed. This report is the result of a one-year stream sampling and testing survey conducted to determine sources of acid mine drainage pollution and to present recommendations for abating this pollution to upgrade the quality of the East Branch Clarion River.

Recommendations as contained in this report present reclamation methods aimed at providing permanent abatement rather than treatment facilities. It is felt the reclamation recommendations contained herein will result in abating approximately 83 percent of the acid mine drainage pollution contributed by some 33 separate sources within the watershed.

We express our appreciation for having been given the opportunity of serving the Department of Mines and Mineral Industries of the Commonwealth on this project.

PROFESSIONAL

MICHAEL BAKER, JR.

ENGINEER

NO. 4690

Very truly yours,

MICHAEL BAKER, JR., INC.

Turing Below, of P.E.

Michael Baker, Jr., P.E. President and Chairman of the Board

# **TABLE OF CONTENTS**

INTRODUCTION	
Description of Engineering Survey Location Description of Drainage Basin Tributary Streams Polluted by Acid Mine Drainage Cultural Features Physiography and Structural Geology Stratigraphy Typical Stratigraphic Section in the Johnson Run Coal Basin Typical Stratigraphic Section in the Clermont Coal Basin History of Coal Mining Operations Previous Water Quality Surveys Present Water Quality Surveys Water Quality Analysis Methods Discussion of Recommended Abatement Measures Sources of Information Selected Bibliography	I-1 I-3 1-3 1-3 1-4 1-5 1-6 1-7 1-8 1-8 1-9 I-11 1-14 1-16
CONCLUSIONS	
Pollution Sources Miles of Polluted Streams Strip-Mining the Main Cause of Pollution Water Quality of the East Branch Clarion River Maximum Acid Discharges Water Quality Indicators C-8 Precipitation Data	C-i C-4 C-6 C-7 C-7 C-8
SUMMARY OF RECOMMENDATIONS	R-1

COST-ANALYSIS X-1 i

### PART II

I

i

<u>PART II</u>	<u>Page</u>
EAST BRANCH CLARION RIVER (MAIN BRANCH)	A-1
Areas 36 and 37 Areas 38, 39, 40 and 41	A-I1 A-12
SWAMP CREEK SUB-BASIN	A-14
Areas 1 and 2 Areas 3 and 4 Area 5 Area 6 Area 7 Area 8 Area 9 Area 12 Area 13 Area 14  Area 26 Area 28 Area 29 Area 31	A-23 A-28 A-33 A-37 A-40 A-43 A-47 A-51 A-56 A-58 A-64 A-66 A-69 A-72
JOHNSON RUN SUB-BASIN	A-75
Area 10 Area 11 Area 18 Area 19 Area 20 Area 21 Area 22 Area 23 Area 24 Area 25 Area 30 Area 33 Area 34	A-89 A-92 A-96 A-98 A-100 A-103 A-108 - A-113 A-116 A-125 A-127 A-130 A-132
BORGARDY RUN SUB-BASIN	A-136

Area 17 A-141 ii

	Page No.
YONKERS RUN SUB-BASIN	A-144
Area 15 A- 152 Area 16 A-155 Area 27 A-158 Area 32	A-161
SMITH RUN SUB-BASIN	A-164
Area 45	A-170
TWOMILE RUN SUB-BASIN	A-174
Area 42	A-179
GUM BOOT RUN SUB-BASIN	A-183
Area 43	A-189
UNPOLLUTED STREAMS	A-193
<u>APPENDICES</u>	
APPENDIX A	
Acid Mine Drainage Pollution Source Area Maps	AA-1
APPENDIX B	
Water Quality Test Data	AB-1
APPENDIX C	
Properties of Coal Mine Refuse Material Area 43D Mine Refuse Bank	AC-2
Acid Producing Properties of Mine Waste Material - Area 24, Pumpkin Hill Road	AC-10

# **ILLUSTRATIONS**

<u>Figures</u>		<u>Page</u>
1 2	Location Map Grading Plan for Part of a Strip-Mined Area	I_2 I-20
3 4	Proposed Burial Method for Coal Mine Waste Isometric Drawing of a Double Bulkhead Grout Seal	I-21 I-22
5	Reconstruction and Soil Treatment of a Section of Pumpkin Hill Road (Township Road 363)	I-23
6	Map Showing Streams Polluted by Acid Mine Drainage	C-5
7	Precipitation Data for Study Period, Glen Hazel	C-11
8	Precipitation Data for Study Period, Clermont	C-12 9
-	on Data, 1951-1960, Glen Hazel	C-13 10
•	on Data, 1961-1970, Glen Hazel	C-14 11
•	on Data, 1951-1960, Clermont	C-15 12
•	on Data, 1961-1970, Clermont	C-16 13
Sketch Ma 14	aps of a Bucktail Mine, August 1883 Sketch Map of Anderson Mine	A-109 A-172
<u>Plates</u>		
I Coal Struc	Acid Mine Drainage Sources ture Contour Map In Pocket	In Pocket II
III	Water Quality Sampling Stations	In Pocket
<u>Tables</u>		
1	Percent of Total Average Daily Acid Load Contributed by Each Source	C-2
2	Estimated Average Daily Acid Mine Drainage Pollution	C-3
3	Water Quality Test Results of Impounded Water in Settling Basins, Coal Processing Plant, 1955	0 0
4	1960 Water Quality Tests, Nashedka Mine, 1948-1960 A-60	A -Z4