

SL-130-1

May 1979



10 DUFF ROAD PITTSBURGH, PA. 15235

DEPARTMENT OF ENVIRONMENTAL RESOURCES

REVIEW NOTICE

This report, prepared by outside consultants, has been reviewed by the Department of Environmental Resources and approved for publication. The contents indicate the conditions that are existing as determined by the consultant, and the consultant's recommendations for correction of the problems. The foregoing does not signify that the contents necessarily reflect the policies, views, or approval of the Department,

TABLE OF CONTENTS

	PAGE
LIST OF TABLES	i
LIST OF FIGURES	i
1.0 INTRODUCTION	1
2.0 MINING HISTORY	3
3.0 FIELD INVESTIGATION	4
4.0 WATER QUALITY SURVEY	5
5.0 RECLAMATION PROCEDURES	7
6.0 RECOMMENDATIONS AND CONCLUSIONS	10
TABLES	
FIGURES	

APPENDIX - CONSTRUCTION DRAWINGS

LIST OF TABLES

<u>TABLE NO.</u> 1	<u>TITLE</u> Water Quality and Pollution Load, State Game Lands No. 117
2	Average pH and Pollution Load, State Game Lands No. 117
2A	Correlation of Sampling Station Numbers, State Game Lands No. 117
3	Revised Recommendation, Areas to be Reclaimed, Preliminary Cost Estimates, State Game Lands No. 117

LIST OF FIGURES

FIGURE NO.	DRAWING NO.	TITLE
1	70-130-A2	State Game Lands No. 117, Vicinity Map
2	70-130-AI	State Game Lands No. 117, Property Map
3	70-130-EIO	Pennsylvania State Game Commission, State Game
	Lands 117, Washington County, Pennsylvania, Area Requiring Reclamation	

LIST OF FIGURES (Continued)

FIGURE NO.DRAWING NO.TITLE470-130-E9Pennsylvania State Game Commission, State GameLands 117, Washington County, Pennsylvania, Water Quality Survey (December 1970)570-130-E8Pennsylvania State Game Commission,

State Game Lands 117, Washington County, Pennsylvania, Water Quality Survey (June 1971, May 1972)

6 70-130-E13 Pennsylvania State Game Commission, State Game Lands 117, Washington County, Pennsylvania, Water Quality Sampling Points and Drainage Basin Boundaries