

## TABLE OF CONTENTS

INTRODUCTION	1-4
DESCRIPTION OF WATERSHED	4 - 8
DRAINAGE	8-10
LAND USE	11-13
METHOD OF STUDY	13-14
INFORMATION SOURCES	14-15
CONCLUSIONS	16-19
RECOMMENDATIONS	20 - 21
POLLUTION SOURCES	22-35
RECAPITULATION OF POLLUTION SOURCES & CONTRIBUTIONS	
TO -LAGOON COMPLEXES	36
SURFACE MINE RECLAMATION	37-63
TREATMENT ALTERNATIVES	64-89
SKETCHES 1,2,3,& 4 - REHABILITATION	90- 94
DESIGN DATA	95-103
COST ESTIMATES	104-113

## <u>APPENDIX</u>

WATER QUALITY	114-129
PRECIPITATION CHARTS FOR YEARS 1968-71	
BASE MAP	PLATE 6965 – P1
STRIP MINE LOCATIONS	PLATE 6965 – P2
PROPOSED TREATMENT FACILITY SITES	PLATE 6965 - P3
MINE OPENINGS	PLATE 6965 - P 4
UNDERGROUND MINE POOLS	PLATE 6965 -P5

## DEPARTMENT OF ENVIRONMENTAL RESOURCES

## **REVIEW NOTICE**

This report, prepared by outside consultants, has been reviewed by the Department of Environmental Resources and approved for publication. The contents indicate the conditions that are existing as determined by the consultant, and the consultant's recommendations for correction. of the problems. The foregoing does. not signify that the contents necessarily reflect the policies, views, or approval of the Department.